

FIRE SAFETY CERTIFICATE

No.207/RFO/FPW/GVMC/2024

DATE: 18.06.2024

Certified that the **VISAKHA VALLEY SCHOOL** building at **Near Old Dairy Farm, Near Zoo Park, Visakhapatnam** comprised of **07 block(s) and 2 (Upper floors)** owned / occupied by **VISAKHA VALLEY SCHOOL** have complied with the fire prevention and fire safety requirements in accordance with the rule of A.P.State Fire Service Rules, and verified by the officers concerned of Fire Service on **14.06.2024** in the presence of **Dr. (Smt).Eshwari Prabhakar** and that the building / premises is fit for occupancy upto classes **XII** with effect from **23.03.2024 to 22.03.2027** for a period of **03** years in accordance with rule and subject to compliance of specific conditions as appended.

1. All the protection arrangements shall be maintained in good condition as seen during inspection.
2. All the escape/exit routes shall not be kept locked/blocked or encroached.
3. All the occupants must know the correct method of operation of the firefighting system installed.
4. All students / staff members of the institution shall be trained to operate the fire safety equipment during emergency.
5. Mock drills should be conducted once in 3 months for initial two years, thereafter, once in every 6 months.

Issued on 18.06.2024 (date of issue) at Visakhapatnam (Place) by

Signature with Seal:

Regional Fire Officer
Fire Prevention Wing
Greater Visakhapatnam Municipal Corporation
Visakhapatnam

Y HANUMANTHA RAO, RFO(YHR)-RFO(TP)-GVMC, O/o
REGIONAL FIRE OFFICER-TOWN PLANNING-GVMC

Name : Y.HANUMANTHA RAO

Designation : Regional Fire Officer

Name & Address of Department / Office:

Fire Prevention Wing, 4th floor, GVMC Zone-IV office,

Beside Venkateswara Theatre, Suryabagh,

Visakhapatnam - 530020.

To,



VISAKHA VALLEY SCHOOL

Near Old Dairy Farm


Near Zoo Park

Visakhapatnam

[Name & Address of the institution]

ENDORSEMENT

The No Objection Certificate issued by Fire Services stands cancelled
an annulled due to non-maintain Fire Safety Measures at all times in
good working condition as seen during inspection.



Y. HANUMANTHA RAO, Regional Fire Officer)